QUARTERLY COMPOSITING OF AIRNET SAMPLES

Purpose

This Meteorology and Air Quality Group (MAQ) procedure describes the preparation of composites of biweekly AIRNET samples for the purpose of determining alpha-emitting nuclides and selected inorganics on a quarterly basis.

Scope

This procedure applies to the preparation and submittal of composited samples of filter papers used to collect airborne particulates as part of the AIRNET monitoring program.

In this procedure

This procedure addresses the following major topics:

Topic	See Page
General Information About This Procedure	2
Who Requires Training to This Procedure?	2
Preparation for Quarterly Sample Compositing	4
Compositing Samples at the Laboratory	6
Records Resulting from This Procedure	9

Hazard Control Plan

The hazard evaluation associated with this work is documented in Attachment 1: Initial risk = **minimal**. Residual risk = **minimal**. Work permits required: none.

First authorization review date is one year from group leader signature below; subsequent authorizations are on file in group office.

Signatures

Prepared by:	Date:		
Ernie Gladney, MAQ		<u>3/29/04</u>	
Approved by:	Date:		
Craig Eberhart, Air Quality Monitoring Project Leader		<u>4/15/04</u>	
Approved by:	Date:		
Terry Morgan, QA Officer		<u>4/15/04</u>	
Work authorized by:	Date:		
		4/15/04	04/15/04

04/15/04

CONTROLLED DOCUMENT

General information about this procedure

Attachments

This procedure has the following attachments:

		No. of
Number	Attachment Title	pages
1	Hazard Control Plan	2

History of revision

This table lists the revision history and effective dates of this procedure.

Revision	Date	Description Of Changes	
0	3/13/2001	New document created from a chapter of ESH-17-	
		202, R12.	
1	7/2/02	Updated details about station 90 handling, cutting	
		filters, and changes to requested analytes.	
2	4/15/04	Updated requirements for disposition and storage of	
		analyzed filters. Discontinued the analysis of rejected	
		biweekly filters not included in normal composite	
		sample.	

Who requires training to this procedure?

The following personnel require training before implementing this procedure:

• MAQ personnel assigned to composite AIRNET samples

Annual retraining is required and will be by self-study ("reading") training.

Training method

The training method for this procedure is **on-the-job** training by a previously trained individual and is documented in accordance with the procedure for training (MAQ-024).

Prerequisites

In addition to training to this procedure, the following training is also required prior to performing this procedure:

 Appropriate Radiation Worker training (as required by the location where procedure is performed)

General information, continued

Definitions specific to this procedure

None.

References

The following documents are referenced in this procedure:

- MAQ-024, "Personnel Training"
- MAQ-202, "Environmental Sampling of Airborne Particulate Radionuclides"
- MAQ-208, "Evaluation of Biweekly AIRNET Data and Calculated Air Concentrations"
- MAQ-AIRNET, "Sampling and Analysis Plan for the Radiological Air Sampling Network (AIRNET)"

Note

Actions specified within this procedure, unless preceded with "should" or "may," are to be considered mandatory guidance (i.e., "shall").

Preparation for quarterly sample compositing

Overview

AIRNET filter samples are collected every two weeks according to procedure MAQ-202. The uncut biweekly samples are shipped to the analytical laboratory for instrumental analysis. Every quarter, the filters from the past calendar quarter are composited into one sample per each AIRNET site for analysis for additional radionuclides and elements. The compositing is done at the laboratory in conjunction with one of that laboratory's staff. Thus, two people commonly perform this process: one to prepare the paperwork and oversee the work, and the second person to handle the samples. See MAQ-AIRNET for more details.

Preparing for quarterly composite

Compositing of the quarterly samples is performed at the analytical laboratory at the end of the quarter after the final set of instrumental analyses is completed. Perform the following steps to prepare needed paperwork for compositing.

Step	Action
1	In the MS Access AIRNET database AIRNET_PeriodID table, there is
	a quarterly composite field, "QuartComp", that will indicate which
	biweekly period IDs will be included in each specific composite. This
	field is populated during each calendar year's start-up activities.
	NOTE : Samples deployed before Christmas and collected in early
	January of the following year will be included in the first quarterly
	composite of the new year.
2	Ensure that the field data V&V for filters and that the biweekly
	analyses are complete.
	NOTE : We elect to take the risk that a few samples may be
	reclassified upon health physics review, and will NOT use the gross
	beta as an indicator for compositing decisions and may composite prior
	to completion of that review.

Steps continued on next page.

Preparation for quarterly sample compositing, continued

Step	Action			
3	Using the MS Access AIRNET database (see the AIRNET Database			
	User's Guide), produce the composite reports to ensure that no sample			
	that has been rejected for field data reasons gets inadvertently included			
	in a composite.			
	• Start on the AIRNET Database Form "MAIN Switchboard" and			
	selecting the "Quarterly Composite" button. The subsequent forms			
	show walk through the process of producing a complete checklist			
	for assembling the composite, printing labels, editing the cover			
	letter, producing a chain-of-custody document for returning			
	samples, etc.			
	Be sure to take a copy of all documents produced via this database			
	form to the compositing site.			
4	Prepare pre-printed labels for the composited samples:			
	• Use the button for that purpose on the AIRNET Database			
	"Quarterly Composite" Form.			
	Be sure to take these to the compositing site.			
5	Prepare a letter to the analytical laboratory by editing the existing			
	template (via the database form) that requests the analyses on the			
	quarterly composite samples. The chemistry data coordinator			
	maintains current analysis information and it is also documented in the			
	Sites_MasterLocation table within the AIRNET database.			

Compositing samples at the laboratory

Compositing the samples

After the filters have been collected, shipped, and analyzed for one quarter, they are ready to be "composited" and submitted for the analyses of various radionuclides by radiochemical alpha spectroscopy. This process will be performed at the analytical laboratory under the direction of MAQ personnel. Follow all safety and radiation protection requirements of the laboratory.

Supplies needed

Collect the materials and tools listed below.

- gloves (powderless)
- scissors
- metal sample cans
- Kimwipes
- 1 set of labels (e.g., "04Q1.nn")
- tweezers

- bench paper
- permanent marker
- scotch tape
- cleaning solution
- Copy of MS Access reports or forms for "Quarterly Composites"

Steps to composite the samples for analysis To composite the samples, perform the following steps:

Step	Action
1	Ensure all required training is complete and current for working in the
	analytical laboratory. The staff from the analytical laboratory will
	work with participating MAQ staff to perform the actual filter cutting
	operation, help track the filters, and record the samples composited on
	the Access report printout. Participating MAQ staff will take legal
	responsibility for the overall compositing process.
2	The analytical lab staff collect all filters (in individual containers) for
	the calendar quarter to be submitted. Refer to the Compositing
	Checklist generated in step three on previous page.
3	For each sample station, label one sample container with the station
	I.D., in the format yyQn.ss, where yy is the year, n is the quarter
	number, and ss is the station number, using the preprinted labels
	generated from the AIRNET database. These labels will be generated
	from the AIRNET database and supplied by the participating MAQ
	staff member.
4	Put all sample containers (each containing an individual filter) from
	each station in an individual stack.

Steps continued on next page.

Compositing samples at the laboratory, continued

Step	Action
5	Refer to the Compositing Checklist generated above and remove all
	samples marked with an "R". Rejected samples will no longer be
	analyzed individually, beginning with the 04Q1 composites. Return
	these rejected samples to LANL for disposition.
6	Refer to the Compositing Checklist and, with the assistance of the
	second person, ensure the stack contains all the period IDs listed on the
	checklist. For each sample that goes in a composite, mark on the
	Compositing Checklist that the samples are present and were included
	in this composite.
7	Cover the bench with bench paper and place a Kimwipe over the
	immediate work area. Put on the gloves. Select one stack (representing
	a single station).
8	Place a labeled sample composite container open, face-up in the
	covered work area. Remove samples one at a time from their original
	counting containers, and holding each over the composite container
	with the tweezers, cut it in half, letting the loose half drop gently into
	the composite container. Place the remaining half (held in the
	tweezers) gently back into its original counting container. Note that as
	a result of changes to the biweekly analysis requirements, that some of
	the stations will have only one-half filter remaining for use in the
	composite. In these cases, simply combine all the remaining half
0	filters WITHOUT any further cutting.
9	If there is remaining loose particulate material in any of the vacated
	individual sample containers, manually apportion it uniformly between
10	the new composite containers.
10	Discard any vacated individual sample containers. Repeat steps 7
	through 9 for the remaining filters in this quarter for this site. Close the completed composite sample container and set aside for
	resubmission to the Sample Management organization at the analytical
	laboratory. If the filters have never left their custody, all chain-of-
	custody documentation is handled internal to the analytical laboratory.
11	Put a new Kimwipe on the work area. Wash both scissors and
11	tweezers. Select the next stack (representing a single station). Repeat
	steps 8 through 10.
12	After the last composite is prepared, both the participating MAQ staff
12	and the analytical laboratory staff must sign and date the Compositing
	Checklist. Make a copy, and leave one copy at the analytical
	laboratory. Ensure the original Quarterly Composite Checklist is
	returned and becomes part of the records retained at MAQ. Leave the
	original (or draft) of the cover letter requesting the specific analyses to
	be performed.

Compositing samples at the laboratory, continued

Step	Action
13	Package all remaining sample half-filters for shipment back to Los
	Alamos. Initiate the C-of-C form that was prepared from the database
	and receive custody of the sample remains from the analytical
	laboratory for return to MAQ. Upon arrival in Los Alamos, relinquish
	custody to the field team at TA-54 site for sample archiving.

Records resulting from this procedure

Records

The following records generated as a result of this procedure are to be submitted **within 1 week** as records to the records coordinator:

• Completed and signed Compositing Checklist. This will generally be a part of a larger internal memo that documents how the quaterly air volumes were calculated.

HAZARD CONTROL PLAN
The work to be performed is described in this procedure.
"Quarterly Compositing of AIRNET Samples"
2. Describe potential hazards associated with the work (use continuation page if needed).
Contamination from handling filters with potential particulate activity.
3. For each hazard, list the likelihood and severity, and the resulting initial risk level (before any work
controls are applied, as determined according to LIR300-00-01, section 7.2)
Improbable / Negligible = Minimal
Overall initial risk: Minimal Low Medium High
4. Applicable Laboratory, facility, or activity operational requirements directly related to the work: None List: Work Permits required? No List:
LID 402 706 01 "Dorgonnal Docimatery"
LIR-402-706-01 "Personnel Dosimetry"

HAZARD CONTROL PLAN, continued
5. Describe how the hazards listed above will be mitigated (e.g., safety equipment, administrative controls, etc.):
Use of appropriate PPE (gloves, lab coat), work done in a controled area. Appropriate radiological monitor available, RCT phone number posted by phone or other readily available location in case of contamination. Follow all requirements of the facility or laboratory where the work is being done.
 6. Knowledge, skills, abilities, and training necessary to safely perform this work (check one or both):
7. Any wastes and/or residual materials? (check one) None List: (Used filter media or analytical residue is disposed by the analytical laboratory.)
8. Considering the administrative and engineering controls to be used, the <i>residual</i> risk level (as determined according to LIR300-00-01.0, section 7.3.3) is (check one): Minimal Low Medium (requires approval by Division Director)
9. Emergency actions to take in event of control failures or abnormal operation (check one): None List: A: Notify ESH-1 RCT for area or other appropriate rad control personnel. B: Use decontamination material such as "Fantastic" cleaner, paper towel, gloves. C: Notify MAQ supervisor.
Signature of preparer of this HCP: This HCP was prepared by a knowledgeable individual and reviewed in accordance with requirements in LIR 300-00-01 and LIR 300-00-02.
Preparer(s) signature(s) Name(s) (print) Name(s) (print